DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-027792 Address: 333 Burma Road **Date Inspected:** 16-Jun-2012

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No

N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:**

Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG/Tower

Summary of Items Observed:

At the start of the shift this Quality Assurance Lead Inspector (QAI) traveled to the SAS project site and observed the work and the inspection performed by American Bridge/Fluor Enterprises (AB/F) Quality Control (QC) personnel. The observations and inspections were performed as noted below:

A). This Quality Assurance Lead Inspector (QALI) assigned the QA Inspectors to the following, but not limited to the work station(s) listed, to observe the welding and the QC inspection of the following:

Joselito Lizardo-OBG W13 Drop-In Panel (Observation of welding, QC inspection and testing of panel splices).

Will Clifford-Tower Shear Plates, ESW "E" (Performed investigative excavation, documentation and observed QC inspection and testing of transverse and longitudinal indications).

Doug Frey-Tower Shear Plates, ESW "F", "J" and "R"(Observation of repair welding, QC inspection and testing).

Rodney Patterson-OBG E13 Drop-In Panel (Observation of production welding, QC inspection and testing of structural steel deck beams).

NOTE: See QA daily Weld Inspection Reports (WIR) and NDE reports for additional information and details.

Quality Assurance Lead Inspector (QALI) Summary

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Lead Inspector (QALI) observed the QA Inspector's Joselito Lizardo, William Clifford, Doug Frey and Rodney Patterson monitor the work performed by the QC inspectors at random intervals and also observed the QA Inspectors verify the welding parameters, the minimum preheat and the maximum interpass temperatures for compliance with the contract specifications. The QAI's utilized a Fluke 337 clamp meter to measure the electrical welding parameters, Tempil Heat Indicators and/or a Fluke 63 IR Thermometer for verifying the preheat and interpass temperatures. At the conclusion of the shift, this QA Lead Inspector discussed and reviewed the work performed by the QAI's in regards to the various observations and the verifications of the WPS's, consumables, welding parameters, preheat and interpass temperatures. The QAI observations of the QC inspection and verification of the welding parameters performed on this date appeared to comply with the contract specifications and no issues were noted.

OBG W13 Drop-In Panels (SPCM)

This QAI observed the Shielded Metal Arc Welding (SMAW) process of the panel field splice identified as Weld Number (WN): 13W-W2.8. The welding was performed by welding personnel, Jeremy Dolman, ID-5042utilizing the Welding Procedure Specification (WPS) ABF-WPS-D15-1040C-CU, Rev. 0. The WPS was also used by the Quality Control (QC) Inspector William Sherwood to verify the welding parameters and to monitor the welding of the Complete Joint Penetration (CJP) groove weld. The QAI observed the QC inspector verifying the welding parameters and were noted as 128 amps. The minimum preheat temperature of 40 degrees Celsius and the maximum interpass temperature of 230 degrees Celsius appeared to comply with contract documents. The welding was performed in the overhead (4G) position with the work positioned in an approximately horizontal plane and the weld metal deposited from the underside.

Later in the shift, this QAI also observed the Shielded Metal Arc Welding (SMAW) process of the panel field splice identified as Weld Number (WN): 13W-14W-A. The welding was performed by welding personnel, Rory Hogan, ID-3186, utilizing the Welding Procedure Specification (WPS) ABF-WPS-D15-1040C-CU, Rev. 0. The WPS was also used by the Quality Control (QC) Inspector William Sherwood to verify the welding parameters and to monitor the welding of the Complete Joint Penetration (CJP) groove weld. The welding and QC inspection was observed by this QAI at random intervals through the course of the shift. The welding was also performed in the overhead (4G) position.

QA Observation and Summary

The QA inspector observed the QC activities and the welding of the field splices utilizing the WPS as noted above, which appeared to be posted at the weld stations. The welding parameters and surface temperatures were verified by the QC inspectors utilizing a Fluke 337 clamp meter for the electrical welding parameters and a Fluke 63 IR Thermometer for verifying the preheat and interpass temperatures. The welding consumables utilized for the SMAW welding process appeared to comply with the AWS Specification and AWS Classification. The QC inspection, testing and welding performed on this shift appeared to be in general compliance with the contract documents. At random intervals, the QAI verified the QC inspection, testing, welding parameters and the surface temperatures utilizing various inspection equipment and gages which included a Fluke 337 Clamp Meter and Tempilstik Temperature indicators.

This QALI continued the daily review of field inspection reports and update of the field document control tracking

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

records regarding the Orthotropic Box Girders (OBG, Longitudinal and Transverse "A" Deck Stiffeners, Deck Access Holes and the Tower Shear plates). Also, this QALI performed survey and prepared update documentation of the East and West OBG.

Summary of Conversations:

There were general conversations with Quality Control Lead Inspector, Bonifacio Daquinag, Jr., at the start of the shift regarding the location of welding, inspection personnel scheduled for this shift.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy 510-385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Reyes, Danny	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer